

Fox Valley Tool & Die, Inc.

Design & Build - Tool & Die - Jig & Fixture - EDM - CNC Machining

Phone: 920-766-9455 Fax: 920-766-9135 Toll Free: 1-888-585-FVTD(3883)

E-mail Address: fvtD@fvtD.com

Website Address: <http://www.fvtD.com>

Cad Data Transfer Information

2D CAD File Import Formats

Pro-Engineer Wildfire 4.0 & 5.0

.DRW • Native Pro E File
.DXF • DXF File
.IGS • IGES File

TekSoft ProCAM II 2004

.PCII • Native TekSoft File
.PRT • Native TekSoft File
.DXF • DXF File
.IGS • IGES File
.DWG • AutoCAD File

SolidWorks 2009 & 2010

.SLDDRW • Native SolidWorks File
.DXF • DXF File
.IGS • IGES File

AutoCAD 2010 & AutoCAD LT 2007

.DWG • Native AutoCAD File
.DXF • DXF File
.IGS • IGES File

3D CAD File Import Formats

Pro-Engineer Wildfire 4.0 & 5.0

.PRT • Native Pro E File
.STP • STEP Files (Solid)
.SAT • ACIS Files (Solid)
.IGS • IGES Files (Surfaces)
.NEU • (Not Release Sensitive)

TekSoft ProCAM II 2004

.PCII • Native TekSoft File (Surfaces)
.3D • Native TekSoft File (Surfaces)
.IGS • IGES File (Surfaces)
.DWG • AutoCAD File

SolidWorks 2009 & 2010

.SLDPRT • Native SolidWorks File
.STP, .STEP • STEP File (Solid)
.IGS • IGES File (Solid)
.X_T, .X_B • Parasolid File (Solid)

Rhino Nurb Surfacing

.3DM • Native Rhinoceros File
.STP • STEP File
.IGS • IGES File
.VGA • VGA File

Secondary manufacture software is available for Pro-E and SolidWorks (Pro-Manufacture, Open Mind, CamWorks, & Esprit).

2D Mazatrol Offline Programming

CamLink GB/GeoEntry

.GEO • Native CamLink File
.DXF • DXF File

Transfer Methods

We use WinZip (.ZIP) for file compression (only necessary on sizeable files).

•Email: [fvtd@fvtd.com](mailto:fvtD@fvtd.com)

•Mail: 3.5" Diskettes, CD-R & CD-RW Compact Discs

•FTP Site: <ftp://ftp.fvtd.com> (Call for ID & password or log onto our website and request one.)